



EUROPEAN TRUCK TRAILER PARTS BVBA

Liebeekstraat 13
8800 ROESELARE
BELGIUM

Tel.: +32 51 26 49 90
Fax: +32 51 26 49 91
Btw: BE 0472 930 329
info@ettp.be
www.ettp.be

HERSTELSET TRAILER- FRUEHAUF SMB KIT REPARATION TRAILER-FRUEHAUF SMB REPAIRKITS FOR TRAILER FRUEHAUF SMB



Cross reference

M010676

Description

Repairkit 2 camshafts SMB up to October 1994.
Tube length 515 mm

ETTP Ref.

M010676-A



Cross reference

M050147

Description

Repairkit 2 camshafts SMB from November 1994.
Tube length 455 mm

ETTP Ref.

M050147-A